
BACKGROUND OF CONTINUOUS CASTING BILLET DEFECTS: FORMATION MECHANISMS AND FAST & EFFECTIVE DETECTION with 5 WHYS METHOD

Ugur CENGIZ Bilecik Demir Çelik Sept. 2024






Challenge: In the Continuous Casting (CC) process, billets often suffer from defects like cracks and inclusions, which can severely impact product quality. Identifying the formation mechanisms of these defects and developing fast, effective detection methods are crucial for minimizing production losses and ensuring high-quality output.





Formation Mechanisms of Defects





Understanding Defect Formation


Longitudinal cracks form in the direction of steel extraction/flow.







and are usually about 1-2 mm deep.


Influence of Steel Chemistry

















RAZI











Characteristics of surface cracks in the bloom: (a) Macroscopic of surface depression-type crack, (b) 3D depth of field of depressions, (c) Dendrite of crack surface, (c1) OM from longitudinal cross section of crack, (c2) SEM from longitudinal cross section of crack https://link.springer.com/article/10.1007/s11663-023-02911-4/figures/2

Influence of Process Parameters & Microstructure Evolution



Prevention

- Metallurgical measures
 - Decrease precipitation start temperature
 - Improve hot ductility
 - Decrease oscillation mark depth
 - +Control residuals (network cracks)
- Operating measures
 - ✦Increase casting speed
- Mold –related measures
 - +Improve lubrication (oil/mold powder)
 - +Decrease oscillation mark depth
- + Secondary cooling
 - +Decrease specific water flowrate






The 5 Whys Method for Root - Cause Analysis

- 1. Why did the crack form?
- 2. Why was the cooling uneven?
- 3. Why weren't the mold conditions optimized?
- 4. Why was there a lapse in real-time monitoring?5. Why wasn't the steel chemical composition not

properly adjusted?







Benefits of Using the 5 Whys Method



Analysis of Transverse and Corner Crack with 5 Why method

WHY? WHAT IS THE SOURCE OF DEFECT? WHY DOES THE DEFECT OCCUR?	HOW TO PREVENT THE DEFECT?	HOW TO DETECT THE DEFECT?	WHAT ARE THE DEFECT REMOVAL METHODS ?	WHAT ARE THI EFFECTS OF TH DEFECT ON TH FINAL ROLLED PRODUCT?
 Incorrect oscillation settings. Solidifying liquid steel getting caught on irregularities inside the mold. Deformation of the mold (excessive tapering, wall wear). Very high steel temperature. Non-uniform secondary cooling water. Severe localized cooling of the strand. Incorrect mold lubrication. Dirty inner surface of 	- Absence of scratches	casting. Only large cracks can be identified. - Grinding in a direction parallel to the cracks can easily reveal the defect. - Inspection performed after acid etching the surface provides very good results.	 If transverse surface cracks occur in one cast, this defect persists throughout the entire casting. If the cracks are not deep, the entire semi- finished surface and corners should be cleaned by grinding or scarfing. If the cracks are deep, the semi-finished product is scrapped. 	 Transverse bill cracks cause larg cracks on the surface of the rolled product. On bar product cracks appear jagged, like a sat blade. Large cracks cat lead to significat rolling problems and may result i the billet breaki or snapping duri rolling.



Fast and Effective Detection Strategies

 Excessive slag in the steel and slag Removing slag from the tould, Skimming the mold, Maintaining Mn/Si ratio 23 and into the mould. Maintaining Mn/Si ratio 23 and into the mould. Maintaining Mn/Si ratio 23 and into the mould. Insufficiency/excess of fubrication, Changing the mold, Changing the casting, Changing the casting, Correctly controlling the casting, Selecting and appropriate flow rate, Correctly controlling area Selecting flow does not flow into the and old center, Stating the sprave colling area Selecting and appropriately using the water pressure high. Selecting and appropriately using the water pressure high. 	WHY? WHAT IS THE SOURCE OF DEFECT? WHY DOES THE DEFECT OCCUR?	HOW TO PREVENT THE DEFECT?	HOW TO DETECT THE DEFECT?	DEFECT REMOVAL METHODS?	WHAT ARE THE EFFECTS OF THE DEFECT ON THE FINAL ROLLED PRODUCT?	+ + + + + + + + + + + + + + + + + + +
 Low tundish level and slag leaking into the mould. Maintaining Mn/Si ratio 2 3 and Al content < 0.005, Insufficiency/excess of lubrication, Excessive use of casting powder, Steed-Jslag adhesion at the mouth Mold deformation, And applopriate flow rate, Costing the proper wold cooling water not at appropriate flow rate, Costing flow does not flow into the mold, Selecting and appropriate flow rate (ring and collector) Instrometer flow rate (ring and collector) Instrometer flow rate (ring and collector) Instrometer flow rate (ring and collector) Adjusting the secondary cooling water flow rate (ring and collector) Adjusting the secondary cooling water flow rate (ring and collector) Instrometer flow rate (ring and collector) Instrometer flow rate (ring and collector) Adjusting the secondary cooling water flow rate (ring and collector) Instrometer flow rate (ring and collector) Instro	adhesion between the mold and the	- Removing slag from the tundish,	resulting from	necessitates	cause various serious	
into the mould. • Insufficiency/excess of lubrication, • Liquid Steel • Liquid Steel • Liquid Steel • An explosion can cause the britteness in the material, • Algusting the proper mold • Adjusting the proper mold cooling water not at appropriate flow rate, • Casting speed, • High casting speed, • Steel flow rate, • Selecting and appropriately using suitable water sprinklers and model, • Designing the spray cooling mater • Casting the cooling water flow rate (ring and the appropriate flow rate, • Steel flow rate, • Correctly controlling the casting • Casting the does on the suitable water sprinklers and nocizes, • Introper selection or clogging of the 1st and 2nd cooling water jets. • Ist and 2nd cooling water pressure high. • Ist and 2nd cooling water jets. •						
 Insufficiency/excess of lubrication, Limiting the amount of S that causes hot brittleness in the material, Steel/slag adhesion at the mouth of the mold, Changing the proper mold cooling water not at appropriate flow rate, Casting flow does not flow into the mold decenter, Statel X and S tage waters not halving. Selecting and appropriate flow rate (ring and cooling water properly aligning the zircon mold, Selecting and appropriate flow rate (ring and cooling water properly aligning the zircon mold, Selecting and appropriate flow rate, in grad appropriate flow rate (ring and cooling water properly, keeping the zircon mold, Selecting and appropriate flow rate, ing and cooling water properly, keeping the spray cooling mater properly, keeping the water pressure high. 						
 Encreasive use of casting provider, Steel/slag adhesion at the mouth of the mold, Mold deformation, Mold deformation, Mold cooling water not at appropriate flow rate, Correctly controlling the casting the mold, Adjusting the proper mold cooling water flow rate, Correctly controlling the casting and appropriately using suitable water sprinklers and mozzle s, Stand Stateg waters not having Designing the spray cooling area so that the cooling intensity decreases from top to bottom, Adjusting the scondary cooling water piets. 		·	Ŭ Ŭ			
 Steel/slag adhesion at the mouth of the mold, Mold deformation, Adjusting the proper mold cooling water not at appropriate flow rate, Correctly controlling the casting chemperature and speed, Properly aligning the zircon mold, Selecting and appropriately using suitable water sprinklers and nozzles, Selecting and appropriate flow rate (ring and colling water if now rate properly, keeping the spray cooling water pressure high. Himproper selection or clogging of the last and 2nd cooling water jets. Adjusting the secondary cooling water pressure high. Strand, leading to a severe burst. An explosion can also cause serious damage to the machine. Properly aligning the zircon mold, Selecting and appropriately using suitable water sprinklers and nozzles, Designing the spray cooling area so that the cooling intensity decreases from to p to bottom, exter pressure high. Aligusting the secondary cooling water pressure high. 	• • • • • • • • • • • • • • • • • • •					
of the mold, • Mold deformation, • Mold cooling water not at appropriate flow rate, • Carectly controlling the casting • Casting speed, • High casting speed, • High casting speed due to zirconia nozzle expansion. • Casting flow does not flow into the mold, • Selecting and appropriately using suitable water sprinklers and nozzles, • 1st and 2nd cooling water jets. • Improper selection or clogging of the 1st and 2nd cooling water jets. • Improper selection or clogging of the 1st and 2nd cooling water jets. • Improper selection or clogging of • Improper selection or clogging of				billet.		
 Mold deformation, Mold cooling water not at appropriate flow rate, Correctly controlling the casting the proper mold cooling water flow rate, Correctly controlling the casting the proper due to zirconia nozle expansion. Casting the due to zirconia nozle expansion. Selecting and appropriately using suitable water sprinklers and nozles, Designing the spray cooling area so that the cooling intensity decreases from to b to bottom, Adjusting the secondary cooling water flow rate properly, keeping the water pressure high. 						
 Mold cooling water not at appropriate flow rate, Cosnectly controlling the casting temperature is too high, High casting speed, Properly aligning the zircon mold, Selecting and appropriately using suitable water sprinklers and nozzles, Designing the spray cooling area so that the cooling intensity decreases from top to bottom, Adjusting the secondary cooling water righ. 					U U I	
 appropriate flow rate, Correctly controlling the casting temperature and speed, Properly aligning the zircon mold, Selecting and appropriately using suitable water sprinklers and nozzle scansary Casting flow does not flow into the mold center, Ist and 2nd stage waters not having Designing the spray cooling areas so that the cooling intensity decreases from top to bottom, Adjusting the secondary cooling water flow rate properly, keeping the water pressure high. 					ends cracks.	
 Casting temperature is too high, High casting speed, High casting speed due to zirconia nozzle expansion. Casting flow does not flow into the suitable water sprinklers and nozzles, Ist and 2nd stage waters not having, Designing the spray cooling area so that the cooling intensity decreases from top to bottom, Adjusting the secondary cooling water jets. 						
 High casting speed, High casting speed due to zirconia nozzle expansion. Casting flow does not flow into the mold center, Ist and 2nd stage waters not having the appropriate flow rate (ring and collector) Improper selection or clogging of the 1st and 2nd cooling water jets. Adjusting the secondary cooling water pressure high. Properly aligning the zircon mold, Suitable water sprinklers and nozzles, Designing the spray cooling area so that the cooling intensity decreases from top to bottom, Adjusting the secondary cooling water pressure high. 			Ŭ, Ŭ			Air Gap
 High casting speed due to zirconia nozzle expansion. Casting flow does not flow into the mold center, Ist and 2nd stage waters not having the appropriate flow rate (ring and collector) Improper selection or clogging of the 1st and 2nd cooling water jets. Mathematical expansion is the water pressure high. 			machine.			
 Selecting and appropriately using suitable water sprinklers and nozzles, Sta and 2nd stage waters not having the appropriate flow rate (ring and collector) Improper selection or clogging of the 1st and 2nd cooling water jets. 						
 Casting flow does not flow into the mold center, 1st and 2nd stage waters not having the appropriate flow rate (ring and collector) Improper selection or clogging of the 1st and 2nd cooling water jets. 						
mold center, • 1st and 2nd stage waters not having the appropriate flow rate (ring and collector) • Improper selection or clogging of the 1st and 2nd cooling water jets. Adjusting the secondary cooling water flow rate properly, keeping the water pressure high.	· · · · · · · · · · · · · · · · · · ·					Radiation
 • 1st and 2nd stage waters not having the appropriate flow rate (ring and collector) • Improper selection or clogging of the 1st and 2nd cooling water jets. • Adjusting the secondary cooling water prossure high. 		-				
the appropriate flow rate (ring and collector) • Improper selection or clogging of the 1st and 2nd cooling water jets. so that the cooling intensity decreases from top to bottom, - Adjusting the secondary cooling water properly, keeping the water pressure high.						
collector) • Improper selection or clogging of the 1st and 2nd cooling water jets. decreases from top to bottom, - Adjusting the secondary cooling water flow rate properly, keeping the water pressure high.	-					
• Improper selection or clogging of the 1st and 2nd cooling water jets. - Adjusting the secondary cooling water flow rate properly, keeping the water pressure high.		. .				
the 1st and 2nd cooling water jets. water flow rate properly, keeping the water pressure high.						
the water pressure high.						
						G
						Corrosion



A breakout in the continuous casting process can be caused by several factors

Conclusion and Recommendations

In conclusion, the Continuous Casting (CC) process, despite its technological advancements and strict adherence to operational norms, remains prone to defects that affect the final quality of steel billets. Key factors influencing defect formation include the chemical composition of steel, process control parameters, and microstructure development during solidification. By applying methods such as the "5 Whys" analysis, we can better understand the root causes of defects and implement strategies to reduce their occurrence. Continuous monitoring and improvement of the CC process are essential to produce high-quality billets and minimize waste and operational losses.

- **Optimization of Chemical Composition:** Adjust and monitor elements like phosphorus, sulfur, and copper to reduce their negative impact on billet quality.
- Process Parameter Control: Maintain optimal casting temperatures, mold tapering, and cooling practices to avoid cracks and other defects.
- Use of Advanced Detection Methods: Implement real-time monitoring and advanced detection technologies to identify potential defects early in the production process.
- **<u>Regular Equipment Maintenance</u>**: Ensure that mold conditions, oscillation settings, and roller alignments are frequently checked and calibrated to reduce mechanical stresses on the billets.
- **Training and Skill Development:** Equip operators with the knowledge and skills to promptly respond to changes in production conditions, ensuring better defect management.

These steps can significantly improve the overall efficiency and quality of the Continuous Casting process.







Ugur CENGIZ, General Manager, Bilecik Demir Çelik +905557924353

u.cengiz@bilecikdemircelik.com.tr



Thank you for your attention. I'm now open to any questions that you may have.

